



# CHH EM1.0 - Environmental Monitoring Results

Period: 9/11/2015 - 3/12/2015

Site: **Glenreagh NSW**

Environment Protection Licence No. **11413**  
 Site Name -As it appears on the licence **COFFS HARBOUR HARDWOODS**  
 Site Address -As it appears on the licence **161 Tallawudjah Creek Road, GLENREAGH, NSW, 2450**

Location	Frequency	Test	Limit		Units	Sample Date	Result	Comments
			min	max				

NRR = No Result Recorded

## Water Monitoring Data

<b>Point 1</b>	6 Monthly	Chromium		0.001	mg/L			
		Copper		0.0014	mg/L			
		Arsenic		0.024	mg/L			
		Boron		0.37	mg/L			
		Total Suspended Solids		50	mg/L			
		pH	6.5	8.8	pH			
<b>Point 2</b>	6 Monthly	Chromium		0.001	mg/L	3/12/2015	0.006	Re-Test
		Copper		0.0014	mg/L	3/12/2015	0.017	Re-Test
		Arsenic		0.024	mg/L			
		Boron		0.018	mg/L	3/12/2015	0.44	Re-Test
		Total Suspended Solids		50	mg/L	3/12/2015	110	Re-Test
		pH	6.5	8.5	pH	3/12/2015	7.11	Re-Test
<b>Point 3</b>	6 Monthly	Chromium		0.001	mg/L	3/12/2015	0.004	Re-Test
		Copper		0.0014	mg/L	3/12/2015	0.017	Re-Test
		Arsenic		0.024	mg/L			
		Boron		0.37	mg/L	3/12/2015	0.47	Re-Test
		Total Suspended Solids		50	mg/L			
		pH	6.5	8.5	pH			
<b>Point 4</b>	6 Monthly	Chromium		0.001	mg/L	3/12/2015	0.005	Re-Test
		Copper		0.0014	mg/L	3/12/2015	0.012	Re-Test
		Arsenic		0.024	mg/L			
		Boron		0.37	mg/L	3/12/2015	0.32	Re-Test
		Total Suspended Solids		50	mg/L			
		pH	6.5	8.5	pH			
<b>Point 5</b>	6 Monthly	Chromium		0.001	mg/L			
		Copper		0.0014	mg/L			
		Arsenic		0.024	mg/L			
		Boron		0.37	mg/L			